Revised 02/03

DUE DATE

ACTION

RECEIVED

CORRES.	CONT	ROL
INCOMING	LTR	NO.

Bill Owens, Governor Douglas H. Benevento, Executive DirEGRRESPONDENCE

Dedicated to protecting and improving the health of the people of Colorado

00116 RFQ3

4300 Cherry Creek Dr. S. Denver, Colorado 80246-1530 Phone (303) 692-2000 TDD Line (303) 691-7700 Located in Glendale, Colorado

http://www.cdphe.state.co.us

Laboratory and Radiation Services Division 8100 Lowry Blvd. Denver, Colorado 80230-6928 (303) 692-3090

Colorado Department of Public Health and Environment

LTF DIST. BERARDINI. J. H BOGNAR, E. S CROCKETT, G. A DECK, C. A DEGENHART, K. R DIETER, T. J. FERRERA, D. W GERMAIN, A. GIACOMINI, J. J. ONG, J. W YLE, J. L ARTINEZ, L. A NAGEL, R. E. NORTH, K PARKER. A. M

RODGERS, A. SHELTON, D. C. SPEARS, M. S. TUOR, N. R. WILLIAMS, J. PARSONS

BROUSSARDA

COR. CONTROL	L.X	<u>.</u>
ADMN, RECORD	×	
PATS/130		

Reviewed for Addressee Corres, Control RFP

Ref. Ltr. #

DOE ORDER # 400February 5, 2003

Mr. Richard DiSalvo Assistant Manager for Environment and Stewardship U.S. Department of Energy, Rocky Flats Field Office 10808 Highway 93, Unit A Golden, CO 80403-8200

RE: Pre-Demolition Survey Report (PDSR) for Building 551 - Approval

Dear Mr. DiSalvo:

The Colorado Department of Public Health and Environment, Hazardous Materials and Waste Management Division has reviewed the PDSR for Building 551, Revision 0 dated December 31, 2002, received on January 30, 2003. Based on the information contained in this PDSR, we are hereby approving the PDSR for B551.

Although we are currently approving this PDSR and have previously concurred with the designation of B551 as a Type 1 facility, it must be noted that even though B551 is not identified as a building with UBC concerns, ER IHSS Group 500-2 includes the northern half of this building. The southern half of B551 was constructed in 1953 and the northern half in the mid-1960s. The potential contamination associated with Group 500-2 includes organics, metals, and Rads that may have been released into the environment adjacent to B551 prior to construction of the northern half of B551. As such, during the demolition of B551, particularly removal of the slab (especially the northern half), appropriate precautions need to be included in the scope of this demolition activity. In addition, ER needs to be consulted and appropriately integrated into these removal activities to allow for sampling as necessary and appropriate characterization of the waste generated.

If you have any questions regarding this correspondence please contact me at (303) 692-3367 or David Kruchek at (303) 692-3328.

Sincerely,

Steven H. Gunderson

RFCA Project Coordinator

Steve Tower, DOE Tim Rehder, EPA Duane Parsons, KH Lane Butler, KH

Administrative Records Building T130G

Cameron Freiboth, KH Dave Shelton, KH Steve Nesta, KH Marla Broussard, KH



ADMIN RECORD IA-A-001276

DOCUMENT CLASSIFICATION REVIEW WAIVER PER CLASSIFILATION OFFICE ternal